

201110-ED054007

Fushan, Helly, Roderick, Lang & Co. Inc., P.C.
 767 Third Avenue, New York, NY 10017-2023
 Atty. Docket No. 02010/HG NAKAJIMA et al

Fed. No. (212) 319-4900

1/15

FIG. 1




FIG. 2




FIG.3




FIG. 4




FIG. 5




FIG. 6




FIG. 7





FIG. 8

STRAIN MEASURING POSITION
(SECTION ON BROKEN LINE)



PROBABLE FRACTURING PORTION

(POSITION OF MARK X ON SIDE WALL PORTION)

FIG. 9




FIG. 10




FIG. 11




FIG.12

DRAWING RATIO : 2.1

CUP HEIGHT : 35mm




FIG. 13





FIG.14

STRAIN MEASURING POSITION

(SECTION ON BROKEN LINE)



PROBABLE FRACTURING PORTION

(POSITION OF MARK X ON SIDE WALL PORTION)

FIG.15

